

Annexure D

BUILDING SAFETY CERTIFICATE

No. 1078/D-2(C1)

Dated: 23/01/2025

It is certified that the existing building CHANDA PUBLIC SCHOOL (name of the building or premises) at DATALA ROAD, RAMNAGAR, CHANDRAPUR, (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	<u>03</u>					

The building is owned/occupied by CHANDA SHIKSHAN PRASARAK MANDAL RUN BY CHANDA PUBLIC SCHOOL CHANDRAPUR (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of P.W.D NO. 1 (Name of Department/ Govt.) on 05/06/2024 (date of inspection) in the presence of DR. ASHOK SURSHARI JINATODE (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 05/06/2024 for a period of 5 YEARS, years in accordance with rule and subject to compliance of the specific conditions as appended.

1. —
2. —
3. —
4. —

Issued on 23/01/2025 at 3:00 P.M. by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail. Ref. out NO. 1078/safety cert/2025 dt. 21/01/2025.

Signature with Seal: Bhattad

Name: Shrikant K. Bhattad

Designation: Sectional Engineer

Name & Address of Department/ Office: Public Works

Sub Division NO. 1

Chandrapur

Sub-Divisional Engineer

Public Works Sub-Dn.No.1

CHANDRAPUR



सत्यमेव जयते

Government of Maharashtra
Office of the Executive Engineer
Public Works Division No.1,
Civil Lines, Nagpur road, Chandrapur

Telephone No. 07172-250245

Email address : chandrapur1.ce@mahapwd.gov.in


No. : 1078 / Safety Certificate / 2025


Date : 21 / 01 / 2025

BUILDING SAFETY CERTIFICATE OF CHANDA PUBLIC (RAMNAGAR) SCHOOL, CHANDRAPUR

Certified that the School building **Chanda Shikshan Prasarak Mandal (Chanda Public School)**, Survey No. 35/4, 36/2, 38/2, 39/4, 364, 47, 48/2/A mouza Chanda Raiyatwari, Chandrapur, Taluka & District Chandrapur has been inspected by me on dated **20.01.2025** and school building found structurally it fit and safe.

This certificate is issued as per request from Er. Swapnil D. Bokade, Plot No. 28, Jayraj nagar, near Gurudwara, Tukum, Chandrapur vide letter no., Date 06.10.2024.


Sub Divisional Engineer
Public Works Sub Division No.1,
Chandrapur


Executive Engineer
Public Works Division No.1,
Chandrapur

1. Copy forwarded to The Er. Swapnil D. Bokade, Plot No. 28, Jayraj nagar, near Gurudwara, Tukum, Chandrapur for favour of information.
2. Copy forwarded to Sub Divisional Engineer, Public Works Sub Division No.1, Chandrapur for information.